

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(1)



92.jpeg

Created: Thu 18 Nov 18:15 2021

Ascott Sentral Kuala Lumpur

Comments

(2)



93.heic

Created: Thu 18 Nov 18:17 2021

Room 1605 guest has IAQ concerns

Comments

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(3)



94.heic

Created: Thu 18 Nov 18:18 2021

Existing unit using FCU with 2 diffuser and 2 return air duct with 6 FCU pre-filter

Comments

(4)



95.heic

Created: Thu 18 Nov 18:19 2021

Test IAQ before installing Viruskeeper is at 33 pm

Comments

(5)



96.heic

Created: Thu 18 Nov 18:21 2021

Secured the floor with protective canvas
Measure the return and diffuser cover .
Pre-cut Viruskeeper to exact size to the cover.

Comments

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(6)




97.heic

Created: Thu 18 Nov 18:23 2021

Apply Viruskeeper end to end (wearing protective gloves) and stick end to end securely

Comments

(7)



98.heic

Created: Thu 18 Nov 18:24 2021

Viruskeeper filter filament are install at the outer cover of the return air duct. Viruskeeper should be replaced when the words aren't visible to sight.

Comments

(8)



99.heic

Created: Thu 18 Nov 18:27 2021

Remove diffuser and clean up with Wypall X80 wipers

Comments

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(9)



100.heic

Created: Thu 18 Nov 18:28 2021

Ensure visible soil are removed

Comments

(10)



101.heic

Created: Thu 18 Nov 18:29 2021

Attached Viruskeeper end to end on the diffuser and stick with double sided tape

Comments

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(11)



103.heic

Created: Thu 18 Nov 18:32 2021

Viruskeeper installed at the diffuser left hand side and return right hand side

Comments

(12)



104.heic

Created: Thu 18 Nov 18:33 2021

FCU pre filter . Wash, clean & air dried

Comments

(13)



105.heic

Created: Thu 18 Nov 19:15 2021

Attached Viruskeeper at the FCU pre-filter and install back at the FCU vents

Comments

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(14)



106.heic

Created: Thu 18 Nov 19:16 2021

Wrap off debris and dirt from the ceiling and dispose safely at waste compactor

Comments

(15)



107.heic

Created: Thu 18 Nov 19:17 2021

45 minutes later Indoor Air Quality index improve to 18 pm

Comments

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(16)



108.heic

Created: Thu 18 Nov 19:18 2021

After 75 minutes IAQ index further improves to very healthy PM 12

Comments

Contact: Billy Yee
Company: Meridian Chem Sdn Bhd
Phone: 0162013770
Email: billyyee@meridianchem.com

Created: Thu 18 Nov 18:15 2021
Location: Ascott Service Residences Sentral Kuala Lumpur
Title: Viruskeeper Installation To Improve IAQ & Eliminate Germs
No. Items: 17

(17)



NANO SILVER TECHNOLOGY

Eliminate harmful bacteria, mold and viruses including SARS COV 2, chemical toxic gases and dust particles.

Stay Safe and Healthy with VirusKeeper filter installed and running.

CLEAN AIR ZONE

VIRUS KEEPER

Protect from fine dust, carcinogenic hazardous gas, ozone, deleterious bacteria (eliminates 99.9%), and contagious viruses

AIRVISION
www.airvision.co.kr



603 - 8061 0080 Scan for further enquiries

AIRVISION *Members*

Created: Thu 18 Nov 19:19 2021

Viruskeeper keeps your loved ones safe and ideally to be monitor and change every 60 -90 days.

109.jpeg

